Section	1	NW	
Date Estal	blished <u>10/27/2005</u>		
Corner	NW		
Marker	Small RR Spike 2" Below Surface		
32.91' W.	to nail/shiner over Flatrock Twp. stone		
36.30' S.E	2. to nail/shiner NW/side power pole		
75.57' S.W	V. to NE corner porch foundation (no field check)		
78.62' S.V	V. to NE corner house foundation (no field check)		
57.62' N.V	<i>W</i> . to "+" south edge manhole rim		
20.30' S.E	E. to "+" SE/side manhole rim		
22 721 G N			

22.73' S.W. to "+" SE/side manhole rim

Section <u>1</u>	N ¹ ⁄4
Date Established 10/27/2005	
Corner <u>N¹/4</u>	
Marker Small RR Spike	
38.77' N.W. to nail/shiner S/side power pole	
45.79' N.E. to notch in west edge of valve box riser	
40.63' N.N.E. to notch in S/side of valve box riser (P)	
16.40' W. to small RR Spike at Flatrock corner	I

Section <u>1</u>	NE
Date Established <u>10/27/2005</u>	
Corner <u>NE</u>	
Marker Small RR Spike	
See SW Corner, Sec. 31, Monroe Twp.	

Section	1		
Date Esta	blished <u>10/27/2005</u>		
Corner	<u>E¼</u>		
Marker	Placed 5/8" Rebar on E/side of Stone angled over high point_		
Stone is 6	" below grade		E1⁄4
57.05' S.S	S.E. to 5/8" iron pin on ditch bank		
66.15' S. t	to W ¹ /4 Post, Sec. 6, Marion Twp. (no field check)		
67.21' S.S	S.W. to "+" NE/side iron gate post W/side of drive	1	I]
40.55' N.V	W. to mag nail NE/side of tree		

2014 Placed witness post 0.5' south of stone.

Section	2	NW	
Date Estal	olished <u>10/27/2005</u>		
Corner	NW		
Marker	Nail/Shiner	_	
80.25' W.I	N.W. to 60d spike NE/side of telephone pole	_	
74.53' W.I	N.W. to "+" north end conc. pipe (P)	_	
86.71' E.N	I.E. to nail/shiner W/side of telephone pole		
70.74' W.S	S.W. to "+" south end conc. pipe (P)	I	<u> </u>

46.43' W. to nail/shiner Flatrock Twp. Corner

Section <u>2</u>	N1⁄4
Date Established 10/27/2005	
Corner <u>N¹/4</u>	
Marker Nail/Shiner	
65.45' W. to S ¹ / ₄ Post, Sec. 35, Flatrock Twp.	
71.53' N.W. to "+" south face iron anchor post	
28.64' S.S.E. to duplex N/side power pole	
87.01' E.S.E. to sawed "+" in west edge of conc. sanitary manhole (P)	

25.02' N.N.E. to sawed "+" SW corner catch basin (P)

Section <u>2</u>	
Date Established 12/8/1986	
Corner <u>W¹/4</u> SE	
Marker Iron Pin beside stone 6" deep	
Use Survey Plat Vol. 6, Pg. 259 for reference	
13.70' S. to duplex in north root of 36" oak (1986 tie)	W¼SE
67.50' W. to SE corner house foundation (1986 tie)	
82.60 N.W. to NE corner house foundation (1986 tie)	

Section <u>3</u>	NW	
Date Established 10/27/2005		
Corner <u>NW</u>		
Marker Nail/Shiner	_	
60.14' W. to PK nail, Flatrock Twp. Stone		
36.82' N.W. to duplex SE/side telephone pole		
32.00' S.W. to duplex NW/side power pole	_	
20.18' N.N.E. to sawed "+" SE corner conc. guard rail anchor		1

63.39' N.W. to sawed "+" in bridge abutment.

Section <u>3</u>	N ¹ ⁄4
Date Established 10/27/2005	
Corner <u>N¹/4</u>	
Marker Nail/Shiner	
64.00' W. to Flatrock Twp. corner (no field check)	
66.84' W.N.W. to nail/shiner SE/side power pole	
104.91' N.N.W. to SW corner house foundation	
100.29' N.N.E. to SE corner house foundation	
60.15' N.E. to near face well casing	

Section	3		
Date Estab	lished <u>10/27/2005</u>		
Corner			
Marker	Small RR Spike		
37.62' N.W	7. to PK nail SE/side power pole	W1⁄4	
14.35' S.W	. to 5/8" iron pin on south side of field drive		

Section	4	NW	
Date Estal	blished <u>10/26/2005</u>		
Corner	NW		
Marker	Nail/Shiner	_	
85.17' W.	to Flatrock Twp. corner	_	
79.87' E.N	.E. to nail/shiner NW/side buried cable marker		
120.30' E.	S.E. to duplex N/side power pole		
66.36' W.S	S.W. to "+" in conc. catch basin top (P)		

92.73' W.S.W. to center USGS benchmark tablet (P)

Section <u>4</u>	 N¼
Date Established 10/26/2005	
Corner <u>N¹/4</u>	
Marker Nail/Shiner	_
79.20' W. to Flatrock Twp. corner	
83.92' E.S.E. to duplex NE/side power pole	
54.15' E.N.E. to mag nail in 24" corr. plastic pipe (P)	

Section <u>4</u>		
Date Established 10/26/2005		
Corner <u>W¹/4</u>		
Marker Iron Pipe w/Cap 8" Below Grade		
37.40' W. to PK nail SW end CMP arch (P)	W1⁄4	
46.10' N.N.E. to PK nail NE end CMP arch (P)		
71.14' S.S.E. to sawed "+" east end headwall (P)		

Section	5	NW	
Date Estab	lished <u>10/26/2005</u>		
Corner	NW		
Marker	Nail/Shiner		
31.28' S.E.	to nail/shiner NW/side power pole		
75.89' W.S	W. to sawed "+" NW corner conc. turn down anchor		
102.23' N.	W. to SW corner conc. barn foundation		
<u>96.41' N. t</u>	o sawed "+" in face of SE corner conc. barn foundation	1	

118.09' W. to Flatrock Twp. corner

Section <u>5</u>	N1⁄4
Date Established 10/26/2005	
Corner <u>N¹/4</u>	
Marker PK Nail (No Head)	
96.45' W. to Flatrock Twp. stone	
100.45' S.E. to nail/shiner NW/side power pole	
45.74' S.E. to mag nail in top of corr. plastic pipe (P)	
38.24' S.W. to mag nail in top of corr. plastic pipe (P)	

74.29' S. to chiseled "+" in agriculture inlet

Section <u>5</u>	_
Date Established 10/26/2005	KW14NW
Corner <u>W¹/4</u> NW	
Marker <u>1/2" Rebar/Iron Pin 3" below edge of pavement.</u>	
Set mag nail over stone 0.23' east of iron pin	
Ties are to mag nail in pavement	
39.59' N.E. to duplex S/side power pole	
24.83' S.S.W. to "+" north end of conc. headwall (P)	I

_39.06' N.W. to new mag nail in CMP (P)

Section	5		
Date Establis	ned 10/26/2005		
Corner W	1/4		
Marker Ire	on Pin 0.40' east of stone. Iron pin is for location purposes o		
Mag nails 10'	NE & SE of top center stone. Ties to center of stone	W1⁄4	
Stone is 5.5' v	vest of west edge of pavement, 12" below grade		
24.50' E. to du	plex S/side power pole		
55.75' S.S.W.	to PK nail in CMP (P)		1

30.62' N.W. to 5/8" iron pin 1' east of pavement (new)

25.34' E. to iron pin w/cap

34.41' N.E. to 5/8" iron pin 1' east of pavement (no field check)

55.76' S.S.W. to PK nail 1' east of west end helical pipe (P)

Section <u>6</u>	NW	
Date Established 4/2/2014		
Corner <u>NW</u>		
Marker <u>RR Spike</u>		
49.65' N.W. to duplex SW/side power pole		
36.38' S.E. to chiseled + in conc. bridge wingwall		
45.22' S.W. to chiseled + in conc. bridge wingwall		
91.38' N.N.E. to duplex W/side power pole		1

 Section
 6
 N¼

 Date Established
 10/26/2005

 Corner
 N¼

 Marker
 Nail/Shiner

 20.86' N.W. to PK nail west end CMP (P)

 23.94' N.E. to PK nail east end CMP (P)

 176.97' W. to S¼ Post, Sec. 31, Flatrock Twp.

Section <u>6</u>			
Date Established 10/26/2005			
Corner <u>W¹/4</u>			
Marker #7 Rebar on north side of stone -	not over point		
Set 5/8" rebar with top over high point of sto	ne	W1⁄4	
Set mag nails 6' NE & SE			
65.18' W.N.W. to sawed "+" SW corner cond	. bridge		
19.27' S.S.E. to sawed "+" in conc. anchor fo	r G.R. turn-down		
14.62' N.N.W. to duplex SW/side guard rail	post		

Section	7	NW	
Date Esta	blished <u>10/28/2005</u>		
Corner	NW		
Marker	RR Spike		
42.50' N.N	N.W. to "+" south end CMP (P)		
<u>53.15 E.S</u>	.E. to duplex N/side power pole		
<u>60.70' S.S</u>	S.E. to duplex E/side power pole		
8.24' S.W	. to mag nail SE/side guard rail post		
20.78' N.V	W. to mag nail SW/side guard rail post		

43.27' S.E. to sawed "+" SE corner catch basin (P)

Section <u>7</u>	N1⁄4
Date Established 10/28/2005	
Corner <u>N¹/4</u>	
Marker Small RR Spike	
60.45' N.W. to mag nail S/side 36" maple	
64.24' E.S.E. to duplex NE/side power pole	
27.86' S.E. to "+" east end RCP (P)	
17.17' S. to "+" west end RCP (P)	II

Section	7		
Date Estab	lished10/27/2005_		
Corner	<u>W¹/4</u>		
Marker	Small RR Spike		
41.98' N.W	7. to 5/8" iron pin on west ditch bank	W¼	
98.85' S.S.	E. to duplex N/side power pole		
37.19' S.W	. to 5/8" iron pin on west ditch bank		

Section <u>7</u>	
Date Established 10/28/2005	
Corner OTHER	
Marker RR Spike 1" Below Surface	
64.89' N.N.E. to duplex E/side power pole	C/L Rd. Y
51.11' E. to duplex NW/side power pole	
28.30' S.W. to duplex SE/side buried cable marker	

Section <u>8</u>	NW	
Date Established 10/28/2005		
Corner <u>NW</u>		
Marker Small RR Spike		
40.83' S.S.W. to sawed "+" south end RCP (P)		
30.21' S.W. to sawed "+" SW corner conc. box		
45.38' N.N.E. to sawed "+" north end RCP (P)		
20.0710 + 1.1 0 W/(1.1 - 1)		

38.97' S.E. to duplex SW/side power pole

Section <u>8</u>	N1⁄4
Date Established 10/28/2005	
Corner <u>N¹/4</u>	
Marker RR Spike	
19.35' S.S.E. to "+" NW corner conc. corner post	
21.40' S.to PK nail W/side wood anchor post (loose)	
18.15' S.W. to mag nail east end corr. plastic pipe (P)	
44.31' W.S.W. to mag nail west end corr. plastic pipe (P)	

Section	8_		
Date Esta	blished <u>10/28/2005</u>		
Corner	W ¹ / ₄		
Marker	Iron Pin		
12.43' W.	N.W. to PK in CMP (P)	W1⁄4	
31.86' E to	o mag nail in south root 15" hickory		
26.25' S.E	. to 5/8" iron pin 3' east of edge of pavement		
			1

Section	9	NW	
Date Estab	blished <u>10/28/2005</u>		
Corner	NW		
Marker	RR Spike		
<u>68.99' E.S</u>	.E. to duplex SW/side power pole		
37.06' S.E	. to duplex NE/side power pole		
46.36' N.N	U.W. to "+" north end 43" x 68" RCP (P)		
48.79' S.S.	W. to "+" south end 43" x 68" RCP (P)	L	

Section 9	 N1⁄4
Date Established 5/17/2013	
Corner <u>N¹/4</u>	
Marker RR Spike - Stone reset 14" below road surface	_
12.94' S.S.W. to sawed "x" in steel GR post	_
22.66' S.E. to sawed "x" in steel GR post	_
33.19' N.E. to 5/8" iron pin at edge of pavement	_
18.38' N.W. to 5/8" iron pin at edge of pavement	

Section <u>9</u>		
Date Established 10/28/2005		
Corner <u>W¹/4</u>		
Marker RR Spike - 1" Below Surface		
64.69' S.S.E. to "+" NW corner catch basin (P)	W1⁄4	
25.04' W.S.W. to "+" south end conc. block headwall (P)		
24.49' W.N.W. to "+" north end conc. block headwall (P)		
53.13' S.E. to duplex NE/side power pole	I	

Section	10	NW	
Date Estab	olished <u>10/28/2005</u>		
Corner	NW		
Marker	RR Spike		
21.50' N.W	V. to sawed "+" SE corner north bridge rail		
82.09 E.N.	E. to duplex NW/side telephone pole		
40.17' S.W	<i>I</i> . to duplex SE/side power pole		
15.75' S.W	V. to "+" in wingwall (P)		

	_
Section <u>10</u>	N1⁄4
Date Established 10/28/2005	
Corner <u>N¹/4</u>	
Marker RR Spike	
48.82' N.E. to duplex NW/side power pole	
22.10' S. to "+" N/side conc. corner post (leaning north)	
22.10' S.W. to "+" east end RCP (P)	
64.08' W.S.W. to "+" east end conc. headwall (P)	
41.85' S.W. to "+" west end RCP (P)	

Section <u>10</u>		
Date Established 10/28/2005		
Corner <u>W¹/4</u>		
Marker RR Spike		
20.38' E.N.E. to duplex S/side wood post (no field check)	W¼	
54.76' S.W. to PK nail NE/side power pole		
26.22' W.S.W. to PK nail north end corr. plastic pipe (P)		
17.09' N.E. to 5/8" iron pin at east edge of pavement		

19.65' S.E. to 5/8" iron pin at east edge of pavement

Section <u>11</u>	NW	
Date Established 10/27/2005		
Corner <u>NW</u>		
Marker <u>RR Spike</u>		
26.22' S.W. to duplex E/side power pole		
24.99' S.E. to mag nail in 8" CMP (P)		

Section <u>11</u>	N¼NW
Date Established 10/28/2005	1 1 / 41 1 1 1
Corner <u>N¹/4 NW</u>	
Marker RR Spike	
47.25' S.S.W. to sawed "+" in ag. inlet	
38.35' E.S.E. to sawed "+" SW corner bridge	
44.14' N.E. to sawed "+" NW corner bridge	
51.09' S.W. to duplex NW/side power pole	

Section	11		N¼
Date Estal	blished <u>10/27/2005</u>		
Corner	N ¹ / ₄		
Marker	Small RR Spike		
65.04' S.W	V. to mag nail north end 15" CMP		
79.21' S.W	V. to "+" top center ag. inlet wall		
20.60' N.E	E. to 5/8" iron pin at north edge of pavement		
9.43' S.E.	to 5/8" iron pin at south edge of pavement	I	

Section <u>11</u>	N ¹ /4NW NE
Date Established 10/27/2005	
Corner OTHER	
Marker RR Spike	
30.28' S.W. to sawed notch top west end 18" CMP drive pipe (P)	
18.65' S. to sawed notch top east end 18" CMP drive pipe (P)	

Section	12	NW	
Date Estab	lished <u>10/27/2005</u>		
Corner	NW		
Marker	Small RR Spike		
62.44' E. to new "+" W/side conc. post (P)			
14.88' S.E.	to "+" south end RCP (P)		
29.33' S.S.	W. to nail/shiner NE/side power pole		
29.14' N.N	.E. to sawed "+" north end RCP (P)		

Section	12	NE
Date Estab	lished <u>10/27/2005</u>	
Corner	NE	
Marker	RR Spike	
33.72' S.E	to "+" top large rock at toe of slope	
<u>53.52' S. te</u>	NW corner Sec. 7, Marion Twp.	
25.35' N.E	. to 5/8" iron pin 3' east of east edge of pavement	
9.15' S.W.	to 5/8" iron pin 1' west of west edge of pavement	

Section	12		
Date Estal	blished <u>10/27/2005</u>		
Corner	<u>W¼</u>		
Marker	Nail/Shiner		
109.30' N.W. to SE corner brick chimney		W1⁄4	
57.84' N.V	V. to nail/shiner SE/side power pole		
23.83' S.E	. to mag nail north end CMP (P)		
32.78' S.W	<i>I</i> . to mag nail south end corr. plastic pipe (P)		I

Section <u>12</u>	
Date Established 10/27/2005	
Corner <u>E¹/4</u>	
Marker <u>RR Spike</u>	
22.22' W. to PK nail west end 18" CMP (P)	E¼
26.48' S.E. to 5/8" iron pin at east edge of pavement	
47.53' S. to W ¹ / ₄ Post, Sec. 7, Marion Twp.	
7.89' N.E. to 5/8" iron pin at east edge of pavement	 I

Section	13	NW	
Date Estab	Date Established 11/2/2005		
Corner	NW		
Marker	Nail/Shiner		
36.63' S.E. to nail/shiner W/side telephone pole			
44.15' N.W. to nail/shiner E/side power pole			
58.01' N.E	. to nail/shiner S/side power pole		
52.01' E. to	o mag nail east end CMP (P)		

32.09' S.E. to sawed "+" NW corner catch basin (P)

Section <u>13</u>		NE
Date Established 11/2/2005		
Corner <u>NE</u>		
Marker <u>RR Spike</u>		
30.52' N.W. to "+" in south wall of drainage structure (P)		
33.17' N.W. to "+" in north wall of drainage structure (P)		
68.13' S.E. to duplex W/side power pole		
119.14' N.N.E. to duplex E/side power pole	<u>U</u>	
78.73' S.E. to "+" in conc. headwall		

Section	13		
Date Estab	lished <u>11/2/2005</u>		
Corner	W ¹ / ₄		
Marker	Nail/Shiner	_	
36.63' S.E.	to nail/shiner W/side power pole	W1⁄4	
44.15' W.N	I.W. to nail/shiner E/side power pole	_	
40.94' N.W	<i>I</i> . to mag nail south end plastic pipe (P)		
10.9111.11		-	

Section <u>13</u>	
Date Established <u>11/2/2005</u>	
Corner <u>E¹/4</u>	
Marker Iron Pin	
42.52' N.E. to "+" SE corner catch basin (P)	E¼
53.29' S.E. to duplex SW/side power pole	
41.33' S. to W ¹ / ₄ Post, Sec. 18, Marion Twp.	
30.40' W. to duplex NE/side power pole	
15.35' W. to "+" south end RCP (P)	
32.92' N.W. to "+" north end RCP (P)	

Section 13	
Date Established 11/2/2005	
Corner <u>E¹/4</u> SE	
Marker RR Spike 3" Below Edge of Pavement	
97.24' S.S.E. to "+" NW corner catch basin (P)	
88.77' S.S.W. to "+" north end conc. headwall (P)	E¼SI
51.39' S.E. to duplex NE/side power pole	

Section	14	NW	
Date Estab	lished <u>11/2/2005</u>		
Corner	NW		
Marker	Small RR Spike		
<u>133.94' N.</u>	N.E. to duplex SW/side power pole		
33.18' S.W. to 5/8" iron pin on west ditch bank (P)			
22.55' S.E	to 5/8" iron pin at east edge of pavement		

Section <u>14</u>	
Date Established 11/2/2005	Kw¼nw
Corner <u>W¹/4</u> NW	, i i i i i i i i i i i i i i i i i i i
Marker RR Spike 6" Below Surface. Set Small RR spike on surface	
20.14' S.E. to 5/8" iron pin 1' east of edge of pavement	
37.57' S.W. to 5/8" iron pin on west ditch bank	
35.82' N.E. to mag nail SW/side corner fence post	
55.29' S.E. to duplex E/side power pole	

Section	14		
Date Estal	blished <u>11/2/2005</u>		
Corner	W ¹ /4		
Marker	Small RR Spike		
28.15' S.E. to "+" NW corner brick catch basin (P)		W1⁄4	
27.84' S.V	V. to mag nail south end corr. plastic pipe (P)		
61.10' W.S	S.W. to mag nail west end 12" corr. metal pipe (P)		
36.83' N.V	V. to mag nail north end corr. plastic pipe (P)	L	<u> </u>

Section <u>15</u>	NW	
Date Established <u>11/2/2005</u>		
Corner <u>NW</u>		
Marker RR Spike 2" Below Surface		
32.03' N.E. to duplex NW/side power pole		
22.55' S.E. to 5/8" iron pin at east edge of pavement		
15.52' W. to mag nail south end 15" corr. plastic pipe (P)		
28.02! N.W. to mag noil north and 15" corr. plastic ning (P)		

28.93' N.W. to mag nail north end 15" corr. plastic pipe (P)

Section	15_		
Date Estab	olished <u>11/2/2005</u>		
Corner	<u>W¹/4</u>		
Marker	Small RR Spike		
52.81' N.E	. to duplex NW/side power pole	W1⁄4	
67.87' S.S.	W. to mag nail in helical pipe at bank line		
54.69' S.E	. to sawed "+" SW corner conc. drive		

Section	16	NW	
Date Estal	olished <u>11/2/2005</u>		
Corner	NW		
Marker	RR Spike 1" Below Surface		
<u>98.03' N.N</u>	I.W. to duplex SW/side telephone pole		
25.83' E. t	o "+" SW corner conc. post		
88.23' N.N	I.E. to duplex in power pole		
<u>16.02' E. t</u>	o sawed "+" SW corner catch basin (P)		

Section <u>16</u>		
Date Established <u>11/2/2005</u>		
Corner <u>W¹/4</u>		
Marker RR Spike		
113.06' N.E. to duplex E/side power pole (new)	W1⁄4	
33.20' S.W. to 5/8" iron pin on west ditch bank		
70.00' S.S.W. to mag nail in east end 10" helical		
20.37' S.E. to 5/8" rebar at east edge of pavement		

Section	16		
Date Esta	blished <u>11/3/2005</u>		
Corner	CENTER		
Marker	Found stone laying flat with other small stones. Also found	,	e
pieces of l	brick & a sea shell under stone. Set stone in upright	,	Center
position &	c cut a "+" on the high point of stone		
91.32' E. t	to sawed "+" in conc. base of "Smith" head stone		
49.75' S.E	. to sawed "+" in conc. base of "Sweeny" head stone	<u>II</u>	
21 (2) 9 9	E to sourced "It " in some home a f "William Class" store		

21.63' S.S.E. to sawed "+" in conc. base o f "William Glass" stone

Section	17_	NW	
Date Establis	shed <u>10/28/2005</u>		
Corner <u>N</u>	NW		
Marker I	ron Pin		
14.75' W.S.V	W. to mag nail west end 10" CMP		
20.33' N.E. t	o iron pin 3 ¹ / ₂ ' east of edge of pavement		
24.52' S.E. to	o iron pin 3' east of edge of pavement		

Section <u>17</u>	11%
Date Established <u>9/14/2018</u>	
Corner N ¹ / ₄	
Marker None	
"Corner destroyed because of ditch excavation."	
Re-established point per survey Vol. 30, Pg. 178.	

Section <u>17</u>		
Date Established 10/28/2005		
Corner <u>W¹/4</u>		
Marker Rebar 3" Below Surface.		
Placed Small RR Spike on surface over iron pin	W¼	
40.12' N.W. to duplex NE/side power pole		
70.13' N.W. to NE corner house foundation		
56.42' W. to SE corner house foundation		

40.82' N.E. to duplex SE/side telephone pole

Section	18_	NW	
Date Establi	shed <u>10/28/2005</u>		
Corner <u>1</u>	NW		
Marker _1	ron Pin angled over Stone. Set mag nails 6' NE & SE		
36.94' S.S.W	V. to PK nail north end CMP (P) (No field check)		
28.60' N.W.	to 5/8" ironpin on west ditch bank (P) (Reset)		
24.03' E. to a	center disk of conc. GPS monument		
26.85' S. to i	ron pin 1' west of edge of pavement		

 Section
 18

 Date Established
 3/23/2018

 Corner
 N½

 Marker
 Iron Pin over Pipe

 Found Pin called out by survey Vol. 33, Pg. 37

 Found Pipe called out by survey Vol. 12, Pg. 148

 Two questionable stones are beside the pin and pipe.

 GPS shot is to iron pin over iron pipe.

 Placed witness post approx. 1' east of Iron Pin

Section <u>18</u>		
Date Established <u>10/28/2005</u>		
Corner <u>W¹/4</u>		
Marker RR Spike		
73.20' N.N.W. to mag nail in north end corr. plastic pipe	W1⁄4	
22.45' N.W. to PK nail in top of headwall		
20.02' E. to iron pin with cap		

Section	19	NW	
Date Estab	lished <u>11/8/2005</u>		
Corner	NW		
Marker	Small RR Spike		
22.90' N.V	7. to 5/8" rebar on west ditch bank (P)		
39.15' N.E	. to small PK nail SW/side power pole		
-			
5			

Section	19_	N ¹ ⁄4
Date Esta	blished <u>11/8/2005</u>	
Corner	<u>N¼</u>	
Marker	5/8" Iron pin over high pt. of stone. Stone is 0.7' below stone	
road surfa	ce & iron pin is 0.5' below road surface.	
Also foun	d iron pipe 3.9' east & 1.0' south of corner stone	
(origin un	known). Ties to iron pin over stone:	
20.27' N.V	V. to iron pin in shoulder	
22.01' S.V	V. to iron pin in shoulder	

Section <u>19</u>		
Date Established <u>11/8/2005</u>		
Corner <u>W¹/4</u>		
Marker RR Spike 3" Below Surface		
38.31' N.E. to PK nail S/side power pole	W1⁄4	
24.76' S.E. to PK nail south end CMP (P)		
30.74' S.W. to new duplex NW/side buried cable marker (P)		

Section <u>19</u>	
Date Established 11/8/2005	
Corner <u>CENTER</u>	
Marker Stone and Iron Pin on Ditch Bank	¥
5/8" iron pin on S/side of stone. I.P. top 0.1' S of high pt. of stone	Center
Set new PK's 10' SE & SW of high point.	
Iron pin is for location purposes only	
8.41' W.N.W. to "+" west end conc. headwall	
3.42' N.W. to "+" east end conc. headwall	
55.75' S.E. to duplex W/side cable marker post	

33.50' S to new "+" NW corner catch basin

Section	20	NW	
Date Estab	olished <u>11/7/2005</u>		
Corner	NW		
Marker	RR Spike 3 ¹ / ₂ ' west of west edge of pav't 6" below stone surf		
25.03' E. te	o iron pin and cap		
31.35' S.E.	to "+" south end of RCP (P)		
32.50' N.E	. to "+" north end of RCP (P)		

Section <u>20</u>	N%
Date Established <u>4/13/2018</u>	
Corner <u>N¹/4</u>	
Marker Stone with Iron Pin beside it	24 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -
Found stone 15" x 10" with 5/8" Iron Pin for locating purposes	
approx. 0.4' north of high point of stone.	
Stone called out in Surveys Vol. 15, Pg. 122 & Vol. 22 Pg. 1	
Old steel post on north side of stone.	
Placed witness post approx. 1' north of high point of stone.	

Placed broken clay tile around stone.

Section <u>20</u>	
Date Established <u>11/7/2005</u>	
Corner <u>W¹/4</u>	
Marker RR Spike 1" Below Surface	
83.62' N.W. to NE corner conc. block house foundation	W1⁄4
39.23' N.E. to duplex SE/side telephone pole	
38.73' S.E. to duplex SW/side power pole	
35.40' S.W. to duplex N/side power pole (new)	

67.73' N.W. to southeasterly corner conc. block foundation

Section <u>20</u>		
Date Established 11/7/2005		
Corner <u>N¼ SW</u>		
Marker Small RR Spike 1" Deep	X	
43.06' N. to duplex E/side power pole	N ¹ /4SW	
112.11' N.N.E. to SW corner conc. block garage foundation (P)		
23.95' S.S.W. to PK nail east end CMP (P)		
33.98' S.W. to PK nail west end CMP (P)		

41.09' S.W. to duplex SE/side power pole

Section <u>20</u>	
Date Established <u>11/7/2005</u>	
Corner <u>CENTER</u>	
Marker <u>RR Spike</u>	
22.25' N.W. to PK nail west end CMP (P)	▲ Center
18.75' N. to PK nail east end CMP (P)	
29.60' N.E. to PK nail east end CMP (P)	
28.74' S.S.E. to mag nail east end plastic pipe (P)	

Section <u>20</u>	
Date Established <u>11/7/2005</u>	
Corner <u>N¼ SE</u>	
Marker RR Spike 1" Below Surface	 x
22.94' S.S.W. to "+" east end RCP (P)	N¼SE
31.36' S.W. to "+" west end CMP (P)	
71.88' S.W. to duplex SE/side power pole	
52.43' W.S.W. to "+" east end conc. headwall (P)	

Section	20		
Date Established	11/7/2005		
Corner <u>OTHER</u>			
Marker PK Nail 2	"Below Surface. Found PK's 6' north and east		
Removed PK 6' north	to avoid confusion		
77.70' S.W. to duplex	W/side power pole (new)	<	
83.57' N.N.E. to dup	lex E/side telephone pole	26.7 CH.	
87.82' N.N.W. to saw	red "+" SW corner block catch basin	F I	

Section	21	NW	
Date Established	11/7/2005		
Corner <u>NW</u>			
Marker Small	RR Spike		
72.99' N.N.W. to '	"+" on conc. headwall		
107.51' N.N.W. to	duplex SW/side power pole		
66.81' E.S.E. to S	W corner house foundation (no field check)		
20.81' W.S.W. to	PK nail E/side power pole	u	I
95.40' N.N.E. to "	+" on conc. headwall		

54.31' S.S.E. to "+" east end headwall (P)

Section <u>21</u>	N1⁄4
Date Established <u>11/7/2005</u>	
Corner <u>N¹/4</u>	
Marker Iron Pin 3' West of Edge of Pavement	
28.99' E. to duplex W/side power pole (new)	
21.11' S.W. to mag nail in 10" alum. pipe (P)	
67.08' N.E. to duplex SE/side telephone pole	
74.59' N.N.E. to mag nail in 8" plastic drive pipe (P)	

Section	21		
Date Estab	lished <u>11/7/2005</u>		
Corner	W ¹ / ₄		
Marker	Found PK over 1" Iron Pin, 5" below surface.		
Removed I	PK, placed Small RR Spike over iron pin	W1⁄4	
Top of RR	Spike is 1" below surface		
37.87' N.E.	to duplex S/side buried cable marker		
23.40' S.E.	to "+" in conc. headwall (P)		
25.99' S.W	. to "+" in conc. headwall		
41.00' S.W	. to duplex SE/side power pole (new)		
30.15' N.N	.W. to "+" in conc. headwall (P)		

Section <u>21</u>		
Date Established 11/7/2005		
Corner <u>N¼</u> SW		
Marker RR Spike 1" Below Surface	x	
90.81' E.N.E. to duplex S/side buried cable marker	N¼SW	
82.65' E.S.E. to duplex N/side power pole		
15.05' N.E. to 5/8" rebar N/side pavement		
67.95' E.S.E. to sawed "+" west end RCP (P)	I	

Section <u>21</u>		
Date Established 11/7/2005		
Corner <u>CENTER</u>		
Marker Iron Pin		
28.44' W. to duplex N/side power pole (new)	Center	
107.53' E. to duplex S/side power pole		
25.87' N.E. to 5/8" iron pin at east edge of pavement		
27.32' S.E. to 5/8" iron pin at east edge of pavement	L]

Section	21		
Date Estab	lished <u>11/7/2005</u>		
Corner	W ¹ /4 SW		
Marker	Small RR Spike		
79.40' N.W	v. to PK nail S/side power pole (new)		
20.46' S.E.	to 5/8" iron pin at east edge of pavement	∕w¼sw	
23.91' S.W	. to 5/8" iron pin at top of ditch bank (P)		

Section <u>22</u>	NW	
Date Established <u>11/7/2005</u>		
Corner <u>NW</u>		
Marker RR Spike 1" Below Surface	_	
26.95' S.E. to duplex NE/side power pole	_	
33.78' S.E. to "+" NW corner new conc. catch basin (P)	_	
25.05' W. to "+" E/side iron anchor post	_	

Section <u>22</u>		
Date Established <u>11/7/2005</u>		
Corner <u>W¹/4</u>		
Marker Small RR Spike		
20.78' W. to duplex S/side power pole	W¼	
19.98' E. to duplex S/side power pole		
57.16' E.S.E. to NW corner house foundation (no fie	ld check)	
70.52' S.E. to SW corner house foundation (no field	check)	

87.89' S.S.E. to sawed "+" NE corner conc. block foundation (P)

Section <u>22</u>		
Date Established <u>11/7/2005</u>		
Corner <u>CENTER</u>		
Marker RR Spike 1" Below Surface	L	_
40.66' N. to duplex W/side power pole		Center
28.05' S. to duplex W/side power pole		
51.34' N.E. to sawed "+" SE corner conc. drive		
64.00' E.S.E. to mag nail in plastic drive pipe (P)	uI	

Section <u>23</u>	NW	
Date Established <u>11/3/2005</u>		
Corner <u>NW</u>		
Marker Small RR Spike		
21.10' S.W. to "+" west end 48" RCP (P)		
52.36' E.N.E. to duplex S/side cable marker post		
41.89' E.S.E. to mag nail east end plastic pipe (P)		

Section 23	N ¹ ⁄4
Date Established 11/3/2005	
Corner <u>N¹/4</u>	
Marker <u>3/4</u> " Iron Pipe/Rebar 15" below edge of pavement	
PK Nails 6' NW & NE	
55.33' W.N.W. to duplex NE/side power pole	
52.93' S.W. to sawed "+" top center wall of ag. inlet	
28.73' N. to mag nail S/side 15" tree	
28.73' N. to mag nail S/side 15" tree	

Section <u>23</u>		
Date Established 11/3/2005		
Corner <u>W¹/4</u>		
Marker RR Spike 1" Below Surface		
59.27' W.N.W. to duplex NE/side buried cable marker	W1⁄4	
62.38' N.N.W. to duplex SW/side power pole		
32.85' S.E. to "+" east end conc. pipe (P)		
32.68' S.S.W. to "+" south end conc. pipe (P)	I	
32.52' S.W. to "+" west end conc. pipe (P)		

Section 23	
Date Established 11/3/2005	
Corner <u>CENTER</u>	
Marker RR Spike 1" Below Surface	¥
29.72' N.E. to duplex SE/side telephone pole	Center
72.32' S. to duplex W/side power pole	
_23.44' N. to duplex W/side power pole	

Section	24	NW	
Date Established	11/3/2005		
Corner <u>NW</u>			
Marker Nail/Sh	iner		
39.47' N.W. to nail	shiner SE/side power pole		
40.14' N.W. to "+"	in north end RCP (P)		
41.73' N.E. to nail/s	hiner SW/side telephone pole		
31.62' S.W. to "+" i	n top conc. junction box (P)	I	

43.09' E.S.E. to "+" east end RCP (P)

	-
Section 24	N ¹ ⁄4
Date Established 11/3/2005	
Corner <u>N¹/4</u>	
Marker Small RR Spike	_
66.54' W.N.W. to duplex NE/side buried cable marker	_
27.35' N.N.E. to "+" north end RCP (P)	_
55.66' E.N.E. to duplex SE/side buried cable marker	
20.56' S.W. to "+" south end RCP (P)	

Section 24		NE
Date Established 11/1/2005		
Corner <u>NE</u>		
Marker RR Spike - 1" Below Surface		
71.20' S.W. to PK nail E/side power pole		
89.90' S.S.E. to duplex W/side cable marker post		
54.84' S.W. to "+" south end RCP (P)		
52.15' N.W. to "+" north end RCP (P)	u	I
41.03' S. to Marion Twp. corner		

Section	24		
Date Estab	lished <u>11/2/2005</u>		
Corner	<u></u>		
Marker	Nail/Shiner		
<u>68.89' W.N</u>	I.W. to PK nail SE/side telephone pole	W1⁄4	
<u>37.62' N.E</u>	. to PK nail SW/side cable marker post		
34.92' S.W	. to PK nail NE/side cable marker post		
<u>38.58' S.E.</u>	to nail/shiner NW/side power pole	I	

Section <u>24</u>	
Date Established 11/2/2005	
Corner <u>CENTER</u>	
Marker PK Nail 1" Below Surface	¥
21.35' N.W. to sawed "+" north end RCP	Center
18.16' N.N.E. to duplex W/side guard rail post	
21.73' S.S.E. to duplex W/side guard rail post	
32.90' S.W. to sawed "+" south end RCP	
71.22' W.S.W. to "+" top center bolt guard rail turndown	

Section 24		
Date Established 11/2/2005		
Corner <u>E¹/4</u>		
Marker RR Spike 3" below surface - 2' west of east edge of pavement		
46.34' S. to W ¹ / ₄ Post, Sec. 19, Marion Twp.		E¼
68.49' S.S.E. to PK nail north end 18" CMP (P)		
36.13' W.S.W. to mag nail south end corr. plastic pipe (P)		
36.71' W.N.W. to mag nail north end corr. plastic pipe (P)	U	I
38.81' N.W. to "+" south end conc. headwall (P)		
25.89' N.E. to "+" SE corner catch basin (P)		
52.10' S.E. to PK nail N/side power pole		

Section	25	NW	
Date Establis	shed <u>11/3/2005</u>		
Corner <u>N</u>	NW		
Marker <u>N</u>	Nail/Shiner		
39.26' W. to nail/shiner E/side power pole			
29.79' N.E. to "+" SE corner new catch basin (P)			
<u>33.50' S.E. to</u>	o duplex SW/side telephone pole		
32.90' S.E. to	o "+" in center of conc. headwall		

Section	25_	A N¼NW	
Date Establish	ed <u>11/9/2005</u>		
Corner <u>N¹</u>	4 NW		
Marker RF	R Spike 2" Below Surface		
23.75' N.W.to 5/8" iron pin at N edge of pavement (4" below e/p)			
85.09' N.E. to duplex N/side power pole (new)			
24.80' S.W.to 5/8" iron pin on S edge of pavement (4" below e/p)			

Section	25_	N¼
Date Estab	lished <u>11/3/2005</u>	
Corner	<u>N¼</u>	
Marker	Small RR Spike	
22.69' N.E.	to PK nail SW/side cable marker post	
19.91' S.W	. to mag nail E/side 18" ash tree	
68.13' E.N.	E. to duplex NW/side power pole	

Section <u>26</u>	NW	
Date Established 11/8/2005		
Corner <u>NW</u>		
Marker RR Spike 2" Below Surface		
13.15' E. to 5/8" rebar 3' off edge of pavement		
24.33' S.W. to 5/8" rebar 3' off edge of pavement		
29.35' N.W. to 5/8" rebar 5' off edge of pavement		

Section 26	
Date Established 11/9/2005	X W¼NE
Corner <u>W¼ NE</u>	
Marker Iron Pin and PK Nails as noted in 1989	
61.68' N.E. to duplex E/side buried cable marker	
100.12' S.S.W. to duplex E/side power pole	
24.82' S.E. to mag nail in plastic pipe at ground line (P)	

Section	26		
Date Estab	lished <u>11/8/2005</u>		
Corner			
Marker	Small RR Spike on surface at west edge of pavement		
27.85' N.E	. to duplex NW/side power pole (new)	W¼	
31.91' W. 1	to duplex N/side power pole (new)		
31.11' S.E.	to 5/8" rebar at east edge of pavement		
		I	I

Section	26	
Date Established 9/1	11/2017	
Corner <u>CENTER</u>		
Marker <u>5/8" Iron Pin - F</u>	Replaced missing RR spike off 6' O/S nail	
6' Offset PK nails NW & SW		Center
27.96' N.W. to duplex NE/s	ide cable marker	
36.60' S.S.E. to PK nail sou	th end CMP (P)	
26.41' S.W. to sawed "+" west end RCP (P)		

10.59' S.E. to sawed "+" east end RCP (P)

Section <u>26</u>	
Date Established 11/8/2005	
Corner <u>W¹/4</u> SE	
Marker Found Stone 18" below field drive	
Found Iron Pin on E/side of stone 16" below field drive.	
Placed new Iron Pin angled over high point of stone.	₩ ¹ /4SE
Set PK's 10' NE and SE	
9.77' W.S.W. to sawed "+" south end RCP (P)	
26.30' N.W. to sawed "+" north end RCP (P)	

Section	26	
Date Estab	lished <u>11/8/2005</u>	
Corner	OTHER	
Marker	Found RR Spike 5" below road surface.	
Placed Small RR Spike on surface		(
73.13' S.S.	E. to "+" east wall catch basin (P)	
16.66' S.W	'. to sawed "+" south end RCP (P)	
17.11' N.W	7. to sawed "+" in tongue of RCP (P)	

Section	27_	NW	
Date Estab	lished <u>11/8/2005</u>		
Corner	NW		
Marker	Small RR Spike		
<u>55.94' N.W</u>	<i>I</i> . to duplex E/side power pole (leaning)		
40.80' N.E. to duplex W/side power pole (leaning)			
<u>53.12' S.E.</u>	to duplex SW/side buried cable marker		
66.12' S.S.	E. to sawed "+" NW corner catch basin (P)		I]
37.07' S.W. to sawed "+" south end RCP (P)			
50.77' N.E	to sawed "+" east end RCP (P)		

Section <u>27</u>	N%
Date Established 11/5/2005	
Corner <u>N¹/4</u>	
Marker Rebar 6" Below Ground	
PK nails 10' NE and NW	
69.95' N.W. to PK SW/side power pole	

Section <u>27</u>		
Date Established 11/8/2005		
Corner <u>W¹/4</u>		
Marker RR Spike 3" Below Surface		
33.77' N.W. to 5/8" iron pin on west ditch bank (P)	W1⁄4	
27.05' E.N.E. to duplex S/side power pole		
58.38' S.E. to "+" NE corner catch basin (P) (new)		
42.63' S.S.W. to PK nail west end alum. pipe (P)	I	
_29.98' S.W. to 5/8" iron pin on west ditch bank		

Section	27_	(
Date Esta	blished <u>10/30/2005</u>	
Corner	CENTER	
Marker	5/8" Iron Pin	U
<u>1</u>		

Section	28_	NW	
Date Estab	lished <u>11/8/2005</u>		
Corner	NW		
Marker	Small RR Spike		
47.88' S.E.	to PK nail N/side power pole		
77.33' S.W	. to duplex W/side power pole		
<u>15.37' W.N</u>	N.W. to mag nail south end plastic pipe (P)		
<u>35.35' N.W</u>	<i>I</i> . to mag nail north end plastic pipe (P)		

Section	28	N1⁄4
Date Established	11/8/2005	
Corner <u>N¹/4</u>		
Marker Iron P	in 4" Below Ground	
32.28' S.W. to "+"	in north end RCP (P)	
34.40' N. to 5/8" i	ron pin 2' east of end guard rail post	
18.72' E. to 5/8" in	on pin at east edge of pavement	

Section	28_		
Date Established	11/8/2005		
Corner <u>W¹/4</u>			
Marker Smal	RR Spike		
32.38' S.W. to du	plex SE/side power pole	W1⁄4	
24.68' S.W. to "+	" west end conc. headwall		
25.40' S.W. to "+	" south end conc. headwall		
25.00' N.W. to "+	" west end conc. headwall		
19.20' N.W. to ce	nter USGS benchmark		
24.20' N.W. to "+	" north end conc. headwall (P)		

Section <u>28</u>	
Date Established 11/8/2005	
Corner <u>CENTER</u>	
Marker Iron Pipe 0.6' below east edge of pavement	¥
46.60' N.E. to 5/8" iron pin on east ditch bank (no field check)	Center
27.67' S.E. to mag nail in alum. pipe at ground line (P)	_
20.40' S.W. to 5/8" rebar at west edge of pavement (P)	_
22.05' N.W. to 5/8" rebar at west edge of pavement (P)	

Section <u>29</u>	NW	
Date Established <u>11/8/2005</u>		
Corner <u>NW</u>		
Marker RR Spike 1" Below Surface		
44.24' N.W. to duplex E/side buried cable marker		
136.42' N.N.W. to duplex SW/side power pole		
103.10' N.N.E. to duplex S/side buried cable marker		
85.10' S.S.W. to duplex W/side power pole		

 Section
 29

 Date Established
 11/8/2005

 Corner
 W¼

 Marker
 RR Spike 3" Deep

 43.80' W.N.W. to duplex NE/side buried cable marker
 W¼

 43.95' N.N.W. to duplex NE/side buried cable marker
 W¼

 24.94' S.E. to duplex SW/side power pole
 E. to duplex SW/side power pole

 62.73' W.S.W. to duplex S/side power pole
 E. to duplex S/side power pole

Section <u>29</u>	
Date Established <u>11/8/2005</u>	
Corner <u>CENTER</u>	
Marker RR Spike 1" Below Surface	¥
24.20' N.W. to "+" south end concrete headwall (new)	▲ Center
36.70' N.W. to "+" north end concrete headwall (new)	
37.14' S.E. to duplex W/side buried cable marker	
37.21' W.S.W. to duplex SE/side power pole (new)	I
38.99' N.E. to duplex S/side buried cable marker	

Section <u>30</u>	NW	
Date Established 11/8/2005		
Corner <u>NW</u>		
Marker RR Spike 1" Below Surface		
18.96' W.N.W. to mag nail south end helical pipe (P)		
20.93' W.N.W. to duplex SE/side buried cable marker		
71.90' N.W. to duplex NE/side power pole		
67.37' N.N.W. to mag nail north end helical pipe (P)	I	
47.16' N.E. to duplex NW/side power pole (leaning)		
35.71' N.E. to mag nail north end CMP (P)		
32.98' N. to Defiance County corner (RR Spike)		

Section <u>30</u>		
Date Established 11/8/2005		
Corner <u>W¹/4</u>		
Marker Small RR Spike		
17.77' W.S.W. to "+" in center conc. headwall	W1⁄4	
63.53' N.N.W. to duplex in SW root of 30" maple		
26.92' N.E. to "+" in center conc. headwall (P)		
29.80' S.E. to "+" in center conc. headwall (P)		

33.02' N.E. to duplex SE/side power pole

	-
Section <u>30</u>	
Date Established 11/8/2005	
Corner <u>CENTER</u>	
Marker RR Spike 1" Below Surface	
10.51' N. to "+" north end VCP (P)	Center
38.24' S.E. to duplex SW/side power pole	_
33.94' N.W. to mag nail SW/side pine tree	

Section <u>31</u>	NW	
Date Established <u>11/21/2005</u>		
Corner <u>NW</u>		
Marker Small RR Spike		
28.54' N.E. to "+" north end RCP (P)		
114.64' N.W. to SE corner brick veneer house		
37.40' N.E. to duplex S/side power pole		
25.54' S.E. to "+" west end conc. headwall (P)		

42.87' S.W. to duplex NW/side buried cable marker

Section <u>31</u>	N ¹ /4NW	
Date Established 3/22/1983	11/41110	
Corner <u>N¹/4 NW</u>		
Marker Ties from 1983. Did not check in 2005.		
18.85' N.W. to 5/8" iron pin at north edge of pavement		
20.13' N.E. to 5/8" iron pin at south edge of pavement		
18.96' S. to duplex N/side telephone pole		
18.96' S. to duplex N/side telephone pole	_	

Section	31	N ¹ ⁄4
Date Estab	lished <u>11/21/2005</u>	
Corner	<u>N¼</u>	
Marker	Small RR Spike	
140.34' E.S	S.E. to duplex N/side telephone pole	
13.43' S.W	7. to 5/8" iron pin at south edge of pavement	
5.83' N.W.	to 5/8" iron pin at north edge of pavement	

Section <u>31</u>		
Date Established <u>11/21/2005</u>		
Corner <u>W¹/4</u>		
Marker RR Spike 2" Below Surface		
29.71' E. to spike S/side wood anchor post	W1⁄4	
17.80' S.W. to 5/8" iron pin at west edge of pavement (P)		
17.88' N.W. to 5/8" iron pin at west edge of pavement (P)		

Section	31		
Date Estab	lished <u>11/21/2005</u>		
Corner	SW		
Marker	RR Spike 2" Below Surface		
20.85' N.E.	to "+" NW corner catch basin (P)		
38.25' S.E.	to duplex E/side telephone pole		
27.38' S.W	. to duplex NW/side power pole	SW	

Section	31		
Date Estab	lished <u>7/2/1975</u>		
Corner	<u>S¼ SW</u>		
Marker	RR Spike - PK's 6' east and 4' south		
61.52' W.S	.W. to duplex N/side 12" maple (1975 tie)		
111.68' S.V	W. to NE corner barn foundation (1975 tie)		
68.74' E.S.	E. to duplex N/side power pole (1975 tie)	S¼SW V	

Section	31_		
Date Estal	lished <u>11/21/2005</u>		
Corner	<u>S¹/4</u>		
Marker	Found RR Spike 6" Below Surface		
Placed Sm	Placed Small RR Spike on Surface		
_75.76' E.S	E. to "+" SE corner catch basin		
<u>17.99' S.S</u>	E. to duplex W/side power pole		S¼
<u>24.40' N.N</u>	.E. to mag nail in 12" helical pipe (P)		<u> </u>

11.69' N.N.W. to duplex E/side power pole

Section	31			
Date Estab	Date Established			
Corner	<u>S¼ SE</u>			
Marker	Did not check 2005.			
RR Spike.	PK's 6' west and south			
57.71' S.E.	. to duplex N/side telephone pole			
78.29' S.W	7. to duplex N/side power pole		S¼SE V	

Section 31		
Date Established 11/21/2005		
Corner <u>SE</u>		
Marker RR Spike 4" Below Surface		
31.72' N. to "+" in conc. block headwall		
32.14' N.E. to "+" in conc. block headwall		
28.90' N.E. to "+" in east end conc. headwall (P)		SE
32.42' N.N.W. to "+" west end block headwall (P)	I	

Section	32	NW	
Date Estab	lished <u>11/21/2005</u>		
Corner	NW		
Marker	Small RR Spike		
61.15' N.N	.W. to duplex NE/side cable marker post		
50.72' N.N	E. to sawed "+" in RCP (P)		
54.62' E.N	.E. to duplex N/side power pole		
22.55' S.E.	to sawed "+" in RCP (P)		

Section <u>32</u>	N1⁄4
Date Established 11/21/2005	
Corner <u>N¹/4</u>	
Marker Small RR Spike	
_30.60' N.W. to duplex SW/side power pole	
67.35' N.E. to PK nail S/side cable marker post	
33.01' E.S.E. to duplex SW/side guard rail end post	
_33.47' S.W. to duplex SE/side brace post	
23.32' S.S.W. to sawed "+" in RCP (P)	
38.85' N.N.W. to sawed "+" in RCP (P)	

Section <u>32</u>			
Date Established <u>11/21/2005</u>			
Corner <u>S¹/4</u>			
Marker Found Iron Pipe 1' Below Ground. PK's 10' SE and SW	_		
Iron pipe has moved 0.1' north due to ditch bank movement.			
Use PK's to re-establish true point			
49.87' E.N.E. to "+" west end conc. headwall (P)	S ¹ /4		
43.08' E. to Putnam Co. corner			
55 APIESE to "II" SW common patch havin (D)			

55.48' E.S.E. to "+" SW corner catch basin (P)

Section	33	NW	
Date Establish	ned <u>11/21/2005</u>		
Corner <u>N</u>	W		
Marker <u>R</u>	R Spike 3" Below Road Surface		
<u>68.67' W.N.W</u>	. to "+" on curb at corner of building		
43.52' S.E. to	NW corner wood post of storage building		
38.15' S.E. to	"+" SW corner catch basin		
26.28' S.W. to	duplex N/side power pole	I <u> </u>	

64.48' S.W. to corner conc. porch slab

Section <u>33</u>	N ¹ / ₄ NW
Date Established <u>11/21/2005</u>	
Corner <u>N¹/4 NW</u>	
Marker RR Spike 4" Below Surface	
22.50' N.E. to "+" north end RCP (P)	
68.45' E.N.E. to duplex S/side power pole	
20.45' S.E. to "+" south end RCP (P)	

Section <u>33</u>	N1⁄4
Date Established <u>11/21/2005</u>	
Corner <u>N¹/4</u>	
Marker RR Spike 4" Below Surface	
29.90' S.E. to "+" south end RCP (P)	
48.08' N.E. to "+" north end RCP (P)	
45.97' N.W. to "+" west end RCP (P)	

Section <u>33</u>	∕\ N¼NE
Date Established <u>11/21/2005</u>	
Corner <u>N¼ NE</u>	
Marker RR Spike 6" Blow Surface	
45.23' N.W. to duplex NE/side power pole	

Section <u>33</u>		
Date Established <u>11/21/2005</u>		
Corner <u>W¹/4</u>		
Marker RR Spike 1" Below Surface		
100.25' N.N.W. to duplex SW/side power pole	W1⁄4	
24.87' S.E. to mag nail 8" from east end plastic pipe (P)		
19.05' S.W. to mag nail 18" from west end plastic pipe (P)		
39.89' N.W. to mag nail 2' from west end plastic pipe (P)		

Section	33_		
Date Estab	lished <u>11/21/2005</u>		
Corner	SW		
Marker	Small RR Spike		
31.48' N.E	to "+" NE corner conc. catch basin (P)		
40.06' S.E.	to duplex NE/side brace pole		
41.61' S.W	. to duplex SE/side power pole	sw	

Date Established 11/10/2005 Corner NW Marker Small RR Spike 83.35' W.N.W. to "+" near SE corner conc. pump pit	
Marker Small RR Spike	
83 35' W N W to "+" near SE corner conc. nump nit	
05.55 W.IV. to + near 5E conter cone. pump pit	
45.40' N.N.W. to "+" north end conc. pipe (P) (new)	
61.57' N.N.E. to PK nail SW/side telephone pole	
40.28' N.E. to PK nail SW/side power pole	
41.62' N.E. to duplex SE/side buried cable marker	
61.30' E.S.E. to "+" NW corner catch basin (P) (new)	
43.01' S.W. to "+" south end conc. pipe (P)	
53.00' E.N.E. to sawed "+" SW corner catch basin (P)	
Section <u>34</u>	N ¹ ⁄4
Date Established <u>11/10/2005</u>	
Corner <u>N¹/4</u>	
Marker <u>1/2</u> " Rebar	
Set PK's 8' NE and NW	
62.49' N.W. to duplex NE/side power pole (new)	
34.99' N. to duplex east side wood post $3'\pm$ south of south e/p.	

Section	34		
Date Esta	blished <u>10/17/2014</u>	K w¼nw	
Corner	W ¹ /4 NW		
Marker	Small RR Spike		
21.88' E.	to duplex S/side power pole		
42.71' S.V	V. to duplex NE side 24" tree root		
45.65' W.	to duplex N/side power pole		
90.87' S.V	V. to NE corner brick house	U	<u> </u>

Section <u>34</u>		
Date Established <u>11/10/2005</u>		
Corner <u>W¹/4</u>		
Marker Small RR Spike		
11.53' W.N.W. to duplex N/side wood anchor post	W1⁄4	
92.80' S.E. to duplex SW/side power pole		
25.80' N.E. to 5/8" rebar at east edge of pavement		

Section <u>34</u>		
Date Established <u>11/10/2005</u>		
Corner <u>W¹/4 SW</u>		
Marker Iron Pin 9" Below Edge of Pavement		
Set Pk's 6' NE and SE		
44.22' N.E. to "+" center conc. block headwall (P)	{w¼sw	
52.82' N.E. to duplex SE/side power pole		
39.72' S.E. to "+" south end RCP (P)	1	

Section <u>34</u>		
Date Established 9/23/2014		
Corner <u>SW</u>		
Marker Small RR Spike		
40.41' N.W. to iron anchor post		
65.58' N.E. to PK nail west side power pole		
43.49' S.E. to duplex SW side power pole	SW	
35.87' S.E. to "+" NW corner conc. catch basin	I	

13.95' W. to NW corner Sec. 3, Palmer Twp., Putnam Co.

Section	34		
Date Esta	blished <u>4/28/2016</u>		
Corner	<u>S¼ SW</u>		
Marker	Iron Pin 10" deep over stone. Brought to surface.		
Placed RI	R spike over Iron Pin		
37.05' S.E	E. to duplex in SW side of power pole		
15.03' S.V	V. to sawed "X" in north end of plastic drainage	S¼SW	
tile near s	outh toe		
u-			

25.85' S.W. to 5/8" iron pin on south edge of pavement

3 foot offset mags located SW & SE of RR Spike

Section <u>34</u>	
Date Established <u>3/1/2016</u>	
Corner <u>S¹/4</u>	
Marker Dug I. Pin - 6" deep. Brought point to surface.	
Placed RR Spike over I. Pin.	
31.76' S.E. to "+" SW corner C.B. (P)	
24.77' S.E. to duplex N/side power pole	S ¹ ⁄4
58.10' S.E. to sawed "+" NE corner conc. drive (P)	
13.4' S.W. to 5/8" iron pin at south edge of pavement	

20.31' E.N.E. to ¹/₂" iron pin 6" below surface (Putnam Co. Corner)

Section <u>34</u>	
Date Established 4/28/2016	
Corner OTHER	
Marker SE Corner, W ¹ / ₂ , W ¹ / ₂ , SE	
Iron pin 8" deep over stone. Brought to surface.	
Placed RR Spike over Iron Pin	
22.35' S.E. to 5/8" iron pin on south edge of pavement	Other
14.57' S.S.E. to duplex in west side of power pole	 <u> </u>

31.00' N.N.E. to duplex in west side of power pole

Section	34		
Date Estal	blished <u>4/28/2016</u>		
Corner	OTHER		
Marker	SW Corner, E ¹ / ₂ , E ¹ / ₂ , SE		
Found sto	ne protruding above ground		
$10' \pm W. t$	o a small tree		
Placed Co	ounty Survey Marker sign south of stone.		Other
			Y

42.30' W.S.W. to sawed "+" west end RCP (P)

44.42' N.E. to duplex SE/side buried cable marker

Section	35_	NW	
Date Estal	blished <u>11/10/2005</u>		
Corner	NW		
Marker	Small RR Spike		
38.63' N.V	V. to duplex SW/side power pole		
50.88' N.V	W. to "+" (new) in 48" RCP (P)		
44.86' N.E	E. to duplex SE/side buried cable marker		
<u>39.25' S.W</u>	V. to "+" in 48" RCP (P)		
49.25' S.W	V. to duplex SE/side power pole		

Section	35	N ¹ /4
Date Esta	blished <u>11/10/2005</u>	
Corner	<u>N¼</u>	
Marker	Small RR Spike	
70.55' S.E	E. to duplex W/side power pole	
<u>37.32' S.S</u>	S.W. to PK nail in south end plastic pipe (P)	
46.50' N.1	N.W. to PK nail in north end plastic pipe (P)	
54.89' E.N	N.E. to duplex NW/side power pole	

Section <u>35</u>		
Date Established11/10/2005		
Corner <u>W¹/4</u>		
Marker Iron Pin 9" Below Edge of Pavement		
PK Nails 6' NE and SE	W1⁄4	
36.55' S.E. to "+" NE corner catch basin (P)		
28.41' S.S.W. to "+" north end conc. headwall (P)		
21.25' N.W. to mag nail in south end plastic pipe (P)		

Section <u>35</u>	
Date Established <u>11/10/2005</u>	
Corner <u>CENTER</u>	
Marker Small RR Spike	
25.84' N.W. to sawed "+" south end RCP (P)	Center
18.40' E.N.E. to "+" NE corner catch basin (P)	
54.58' S.S.E. to duplex SW/side power pole	
32.14' S.W. to PK nail east end CMP (P)	

59.58' N.N.W. to "+" north end RCP (P)

Section <u>35</u>		
Date Established <u>11/10/2005</u>		
Corner <u>SW</u>		
Marker Iron Pin12" Below Grade on Field Line		
52.80' E. to NW corner, Sec. 2, Palmer Twp., Putnam Co.		
26.42' E.S.E. to 5/8" iron pin on west ditch bank		
42.95' E.N.E. to mag nail in center of pavement	sw	
69.95' N.E. to mag nail in center of pavement	I	I

Section <u>35</u>		
Date Established <u>11/10/2005</u>		
Corner <u>S¼</u>		
Marker Found Rebar and Stone at noted in 1975	_	
Set mag nails 15' NE and SE	_	
Ties are to top center of stone		
65.48' N.E. to new duplex W/side power pole		S1⁄4
59.45' S.E. to "+" in bell of CIP (P)		
92.00' S. to duplex W/side buried cable marker	_	
22.72' S.W. to PK nail west end CMP (P)	_	

12.59' W.N.W. to mag nail in center of pavement

Section <u>35</u>	
Date Established 11/10/2005	
Corner OTHER	
Marker Northwest Corner, Sec. 2, Palmer Twp., Putnam Co.	
Iron Pin 2.5' east of east edge of pavement	
34.95' W.S.W. to 5/8" iron pin on west ditch bank	—— Putnam Co. Sec. 2
52.80' W. to SW corner, Sec. 35, Pleasant Twp.	NW Cor. 52.80'V
79.63' S.S.E. to mag nail west side buried cable marker	p2.80 V
70.28' N.N.W. to mag nail in center of pavement	

Section	36	NW	
Date Estal	blished <u>11/9/2005</u>		
Corner	NW		
Marker	Nail and Shiner		
<u>39.00' N.V</u>	V. to nail/shiner SE/side power pole		
<u>43.24' N.E</u>	. to duplex S/side brace pole (new)		
40.50' S.W	/. to nail/shiner NE/side power pole		
35.30' S.W	V. to "+" south end CMP (P)	I	

52.16' N.W. to "+" north end CMP (P)

Section <u>36</u>	A N¼NW	
Date Established 10/20/1999		
Corner <u>N¹/4 NW</u>		
Marker RR Spike		
9.15' S.S.E. to "+" east end headwall (P)		
18.83' S.W. to "+" west end headwall (P)		
31.25' N.N.W. to "+" north end 48" concrete pipe (P)		

Section	36	N1⁄4
Date Estab	lished <u>11/9/2005</u>	
Corner	<u>N¼</u>	
Marker	RR Spike	
31.66' S.E.	to 5/8" iron pin on south ditch bank (P)	
11.22' N.N	.E. to 5/8" rebar at north edge of pavement	
32.23' S.W	. to 5/8" rebar	

Section <u>36</u>	NE
Date Established 8/19/2020	
Corner <u>NE</u>	
Marker RR Spike - 1" Below Surface	
36.68' N.W. to "+" north end 84" CMP (P)	
48.93' N.W. to duplex SW/side power pole	
36.00' S.E. to duplex W/side buried cable marker	
34.56' S.W. to "+" south end 84" CMP (P)	

44.84' S.W. to duplex NE/side telephone pole

Section <u>36</u>		
Date Established 11/9/2005		
Corner <u>W¹/4</u>		
Marker Nail/Shiner in Power Pole		
41.82' N.W. to nail/shiner in power pole	W1⁄4	
37.28' N.E. to nail/shiner in power pole		
31.06' E.S.E. to "+" in NE corner catch basin (P)		
19.82' S.W. to nag nail in plastic pipe at ground line (P)		

36.71' S.E. to nail/shiner W/side power pole

Section	36	
Date Esta	blished <u>11/9/2005</u>	
Corner	CENTER	
Marker	Found Stone and Iron Pin on Surface of Stone Road	
Ties to St	one:	Center
19.76' S.E	E. to "+" east end of clay tile (new)	
32.18' S.V	<i>W</i> . to 5/8" iron pin on south ditch bank	
8.72' N. to	o 5/8" iron pin 3" below surface	I

Section	36		
Date Esta	blished <u>11/9/2005</u>		
Corner	<u> </u>		
Marker	Iron Pin 1 ¹ / ₂ ' west of west edge of pav't and 8" below surface		
31.29' S.E	E. to duplex S/side wood post		E¼
38.38' S.V	V. to sawed "+" south end RCP (P)		
48.64' N.V	W. to sawed "+" north end RCP (P)		
37.61' N.V	W. to duplex SW/side power pole	1	

Section 36 **Date Established** 11/9/2005 SW Corner Marker Found Stone on ditch bank. Top of stone at grade. Found RR Spike on east side of stone. Ties to top center of stone 37.23' N.W. to nail/shiner E/side power pole (P) 80.70' E.N.E. to nail/shiner W/side power pole SW 69.20' E.S.E. to nail/shiner NW/side telephone pole 73.29' S.E. to "+" NW corner catch basin (P) 29.42' E. to Putnam Co. Corner (R.R.S.) 47.37' S.W. to mag nail in plastic pipe at ground line (P) $16' \pm$ to west edge of pavement of S.R. 108 Section 36 **Date Established** 11/9/2005 Corner S1/4 Iron Pin 6" Below Edge of Pavement Marker PK's 6' NW and NE 21.58' N. to PK nail W/side corner post 113.83' E.N.E. to duplex SW/side power pole (new) S1⁄4

Section	36	
Date Estal	blished <u>4/26/1983</u>	
Corner	OTHER	
Marker	RR Spike - Did Not Check 2005	
31.29' S.E	. to 5/8" iron pin on south ditch bank (P) (1983 tie)	
26.95' S.W	V. to 5/8" iron pin on south ditch bank (P) (1983 tie)	
-		

Section 36		
Date Established 4/25/1983		
Corner OTHER		
Marker RR Spike - Did Not Check 2005		
34.05' N.W. to 5/8" iron pin on north ditch bank (1983 tie)		
28.79' N. to duplex W/side power pole (1983 tie)		
31.89' S.W. to duplex SE/side telephone pole (1983 tie)		
	I	I